

O-WSW - Wing Screws with Washer



Details:

- **Material:** Nylon 6.6
- **Colour:** natural

Symbol	Thread d	Thread length l	Head diameter D	Head height l ₁	Material	Color	Standard pack
		[mm]	[mm]	[mm]			[szt./pcs]
O-WSW-M4-06	M4	6	16	10	PA 66	natural	1000
O-WSW-M4-08	M4	8	16	10	PA 66	natural	1000
O-WSW-M4-10	M4	10	16	10	PA 66	natural	1000
O-WSW-M4-12	M4	12	16	10	PA 66	natural	1000
O-WSW-M4-15	M4	15	16	10	PA 66	natural	1000
O-WSW-M4-20	M4	20	16	10	PA 66	natural	1000
O-WSW-M4-25	M4	25	16	10	PA 66	natural	1000
O-WSW-M4-30	M4	30	16	10	PA 66	natural	1000
O-WSW-M4-40	M4	40	16	10	PA 66	natural	1000
O-WSW-M5-06	M5	6	16	10	PA 66	natural	1000
O-WSW-M5-08	M5	8	16	10	PA 66	natural	1000
O-WSW-M5-10	M5	10	16	10	PA 66	natural	1000
O-WSW-M5-15	M5	15	16	10	PA 66	natural	1000
O-WSW-M5-20	M5	20	16	10	PA 66	natural	1000
O-WSW-M5-25	M5	25	16	10	PA 66	natural	1000

Symbol	Thread d	Thread length l	Head diameter D	Head height l ₁	Material	Color	Standard pack
		[mm]	[mm]	[mm]			[szt./pcs]
O-WSW-M5-30	M5	30	16	10	PA 66	natural	1000
O-WSW-M5-40	M5	40	16	10	PA 66	natural	1000
O-WSW-M6-08	M6	8	25	12	PA 66	natural	1000
O-WSW-M6-10	M6	10	25	12	PA 66	natural	1000
O-WSW-M6-12	M6	12	25	12	PA 66	natural	1000
O-WSW-M6-15	M6	15	25	12	PA 66	natural	1000
O-WSW-M6-20	M6	20	25	12	PA 66	natural	1000
O-WSW-M6-25	M6	25	25	12	PA 66	natural	1000
O-WSW-M6-30	M6	30	25	12	PA 66	natural	1000
O-WSW-M6-40	M6	40	25	12	PA 66	natural	1000
O-WSW-M6-50	M6	50	25	12	PA 66	natural	1000
O-WSW-M6-60	M6	60	25	12	PA 66	natural	500
O-WSW-M6-80	M6	80	25	12	PA 66	natural	500
O-WSW-M8-08	M8	8	25	12	PA 66	natural	1000
O-WSW-M8-10	M8	10	25	12	PA 66	natural	1000
O-WSW-M8-16	M8	16	25	12	PA 66	natural	1000
O-WSW-M8-20	M8	20	25	12	PA 66	natural	1000
O-WSW-M8-25	M8	25	25	12	PA 66	natural	1000
O-WSW-M8-30	M8	30	25	12	PA 66	natural	1000
O-WSW-M8-35	M8	35	25	12	PA 66	natural	1000
O-WSW-M8-40	M8	40	25	12	PA 66	natural	1000
O-WSW-M8-50	M8	50	25	12	PA 66	natural	500
O-WSW-M8-60	M8	60	25	12	PA 66	natural	500
O-WSW-M8-70	M8	70	25	12	PA 66	natural	500
O-WSW-M8-80	M8	80	25	12	PA 66	natural	500
O-WSW-M10-16	M10	16	25	12	PA 66	natural	500
O-WSW-M10-20	M10	20	25	12	PA 66	natural	500
O-WSW-M10-30	M10	30	25	12	PA 66	natural	250
O-WSW-M10-40	M10	40	25	12	PA 66	natural	500
O-WSW-M10-50	M10	50	25	12	PA 66	natural	250
O-WSW-M10-60	M10	60	25	12	PA 66	natural	250
O-WSW-M10-80	M10	80	25	12	PA 66	natural	250
O-WSW-M12-16	M12	16	25	12	PA 66	natural	1000
O-WSW-M12-20	M12	20	25	12	PA 66	natural	500
O-WSW-M12-30	M12	30	25	12	PA 66	natural	500
O-WSW-M12-40	M12	40	25	12	PA 66	natural	500
O-WSW-M12-50	M12	50	25	12	PA 66	natural	250
O-WSW-M12-80	M12	80	25	12	PA 66	natural	250